Feltnova

High-Grip Folder and Carrier Belts

Coating selection guide for demanding transfers



What to check on the line

1. Identify where blanks slip, shift or fail to release. Include the steepest incline and the fastest start or stop in the test.

2. Compare candidate coatings on the actual carton finish. Check for marking at maximum contact pressure and clean release at the discharge point.

3. Confirm the coating, tension member and joining method against the machine requirements before ordering.