Feltnova

Inclined Produce Handling

Sidewalls and cleats checklist

1. Record the crop size, bulk density and required capacity.

2. Match cleat spacing, sidewall height and incline to product behavior.

3. Allow clearance at loading and discharge points.

4. Check cleanability, belt tracking and profile condition during routine maintenance.

General selection guidance. Confirm specifications for your application.