FELTNOVA

Chocolate Transfer Application Brief

Record chocolate temperature and surface condition at transfer.

Measure transfer gaps, roller diameters and available support.

Review cooling conditions and expected changes in product firmness.

Check release using representative products and line speeds.

Provide photographs or a line drawing to Feltnova for application review.