Feltnova

Transfers and Inspection

Application planning guide



Control transfers

Check the gap, nose-bar or pulley diameter, belt speed and product stability at every handover.

Support inspection

For checkweighing, optical inspection and robotic picking, evaluate belt consistency, vibration, contrast and product presentation with the equipment supplier.

Validate in operation

Trial representative products at operating speeds. Record tracking, rejects and cleaning results before final specification.